

# New Jersey Department of Transportation

## FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM	Project ID Numbers	
	DB No.	TIP No.

---

<b>33</b>	<b>Bentley Brook, Drainage</b>	93247	93247
-----------	--------------------------------	-------	-------

**LOCATION/DESCRIPTION**

Vicinity of Bentley Brook, proposed drainage improvement

An identified drainage problem at Bentley Brook results in periodic flooding during heavy rains. Conditions noted include downstream constriction of Bentley Brook.

SPONSOR: NJDOT

COUNTY: Middlesex

MILEPOSTS: 17.30

STRUCTURE NO.: N/A

MPO	Phase	Year
NJTPA	FA	2002
NJTPA	FA	2003

---

<b>33</b>	<b>Conrail Bridge</b>	9101	
-----------	-----------------------	------	--

**LOCATION/DESCRIPTION**

Bridge over Conrail, proposed replacement

This project will provide for the proposed bridge replacement.

SPONSOR: NJDOT

COUNTY: Mercer

MILEPOSTS: 7.70

STRUCTURE NO.: 1113150

MPO	Phase	Year
DVRPC	FA	2002
DVRPC	FSD	2003

# New Jersey Department of Transportation

## FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM	Project ID Numbers	
	DB No.	TIP No.

---

<b>33</b>	<b>34</b>	<b>Wall Township Circle</b>	98485	98485
-----------	-----------	-----------------------------	-------	-------

**LOCATION/DESCRIPTION**

Route 33 and Route 34 traffic circle, identified safety problem

On the basis of statistical analysis, this location has been identified by the Safety Management System as having an apparent safety problem.

SPONSOR: NJDOT

COUNTY: Monmouth

MILEPOSTS: 36.23

STRUCTURE NO.: N/A

MPO	Phase	Year
NJTPA	FA	2002
NJTPA	FSD	2003

---

<b>130</b>	<b>33</b>	<b>Hankins Road/Conover Road</b>	9158	
------------	-----------	----------------------------------	------	--

**LOCATION/DESCRIPTION**

Intersections of Hankins Road and Conover Road, planning study

It is proposed to align Conover Road with the existing signalized intersection of Hankins Road and Route 130. Direct left turns will be provided on all approaches.

SPONSOR: NJDOT

COUNTY: Mercer

MILEPOSTS: 66.40 - 66.90

STRUCTURE NO.: N/A

MPO	Phase	Year
DVRPC	FA	2002
DVRPC	FSD	2003